

## PRODUCT PERFORMANCE TESTING LABORATORY

100 Clemson Research Blvd., Anderson, SC 29625
Phone 864.646.8453 Fax 864.646.2821
Email testing@tcnatile.com Web www,TCNAtile.com

TCNA TEST REPORT NUMBER:

TCNA-0638-17

**PAGE: 1 OF 3** 

**TEST REQUESTED BY:** 

Cepac Tile

**TEST METHOD:** 

Mohs' Scratch Hardness

This test method is used to determine the scratch hardness of a tile surface using the Mohs' hardness scale. A scratch test is performed at each level of hardness to determine the hardness of the surface relative to the Mohs' scale.

**TEST SUBJECT MATERIAL:** 

Identified by client as: "Continental Subway COS-1"

Approximate Size as Received: 3"x6"

**TEST DATE:** 

6/27/2017

## **TEST PROCEDURE NOTES:**

• Sample prep: None

• Three whole tiles were tested.

• The tiles were tested using a Deluxe Hardness Pick Set from Mineralab, LLC. The following minerals are used as standard:

1 – Talc	6 – Feldspar
2 – Gypsum	7 – Quartz
3 – Calcite	8 – Topaz
4 – Fluorite	9 – Corundum
5 – Apatite	10 – Diamond

## **TEST RESULTS:**

The Mohs Scratch Hardness was determined to be as follows:

Tile Sample #	Mohs Scratch Hardness
1	7
2	7
3	7

**COMMENTS:** None