

## PRODUCT TESTING SERVICE

100 Clemson Research Blvd. Anderson, SC 29625 Tel (864) 646-TILE Fax (864) 646-2821

TCNA TEST REPORT NUMBER:

TCNA-077-14

PAGE: 1 OF 1

TEST REQUESTED BY:

Cepac Tile

TEST SUBJECT MATERIAL:

Identified by client as: "CR-1"

TEST DATE:

3/12/2014

**TEST PROCEDURE:** 

## **MOHs Scratch Hardness**

-Three whole tiles were tested.

-The tiles were tested using a Deluxe Hardness Pick Set from Mineralab, LLC. The following minerals are used as standard:

1 - Talc

2 - Gypsum

3 – Calcite

4 - Fluorite

5 - Apatite

6 - Feldspar

7 - Quartz

8 - Topaz

9 – Corundum

10 – Diamond

TEST RESULTS:

The Mohs Scratch Hardness was determined to be as follows:

Tile Sample #	Mohs Scratch Hardness
1	7
2	7 .
3	7

Katelyn Simpson

3/20/2014

Laboratory Manager