

PRODUCT TESTING SERVICE

100 Clemson Research Blvd. Anderson, SC 29625 Tel (864) 646-TILE Fax (864) 646-2821

TCNA TEST REPORT NUMBER:

TCNA-077-14

PAGE: 1 OF 1

TEST REQUESTED BY:

Cepac Tile

TEST SUBJECT MATERIAL:

Identified by client as: "RT-143M"

TEST DATE:

3/12/2014

TEST PROCEDURE:

MOHs Scratch Hardness

- -Three whole tiles were tested.
- -The tiles were tested using a Deluxe Hardness Pick Set from Mineralab, LLC. The following minerals are used as standard:
 - 1 Talc
 - 2 Gypsum
 - 3 Calcite
 - 4 Fluorite
 - 5 Apatite
 - 6 Feldspar
 - 7 Quartz
 - 8 Topaz
 - 9 Corundum
 - 10 Diamond

TEST RESULTS:

The Mohs Scratch Hardness was determined to be as follows:

Tile Sample #	Mohs Scratch Hardness
1	7
2	7
3	7

3/20/2014

Katelyn Simpson Laboratory Manager